

STRUCTURAL STABILITY CERTIFICATE


NAME OF BUILDING: ADMINISTRATIVE BUILDING (G+1 STORIED BUILDING),
NOTRE DAME SISTERS SOCIETY, AT GANDHI ROAD, WEST POINT, P.S. SADAR,
DIST: DARJEELING,
LAND SCHEDULE: MOUZA - DARJEELING, J.L. NO-24, SHEET NO: 45, KHATIAN NO.
5633


We had inspected the above referred structure with a view to ascertain the Structural Stability of the building. The structural elements inspected included foundations, load bearing walls, RCC beams, and wooden slabs, truss. We had also gone through the architectural drawings available for the existing structure. We had also carried out a number of Non-Destructive Tests to estimate the present strength of concrete, and compressive tests are conducted on existing materials and found satisfactory. As per the visual inspection no Cracks are found in wall, beam, stair, plinth level and No settlements in the foundations. The First floor slab (Wooden floor) is safe as per the load test result. We have worked out a system for correcting the distress of the structure and providing necessary strengthening measures.

We therefore certify that the said building structural work is safe and stable for the building user as mentioned in this Stability for Three (03) Years.

NOTE: If earthquake is occurred at the Richter scale of 5.0 or more, it is necessary to conduct revalidation of Structural Stability Certificate as soon as possible.


Er. SAMIT BISWAS
B.Tech (Civil), B.Arch, F.I.V
Bar & Empanelled Valuer, Building Planner
Member of Institution of Valuer No. 1-17335
SMC Regd No B-04, S.D.A.P. No. B-16
Cell 943410249 9832066425


RAJEN KOLEY
B.E (CIVIL), M. Tech
STRUCTURAL ENGINEER
EMPANELLED NO: ESE/11/593
KOLKATA MUNICIPAL CORPORATION

ATTESTED

Principal
Notre Dame Academy
Darjeeling

STRUCTURAL STABILITY CERTIFICATE

NAME OF BUILDING: MIDDLE SCHOOL (FOUR STORIED BUILDING),NOTRE DAME SISTERS SOCIETY, AT GANDHI ROAD, WEST POINT, P.S. SADAR, DIST: DARJEELING,

LAND SCHEDULE: MOUZA - DARJEELING, J.L. NO-24, SHEET NO: 45, KHATAN NO. 5633

We had inspected the above referred structure with a view to ascertain the Structural Stability of the building. The structural elements inspected included foundations, RCC columns, RCC beams, and RCC slabs. We had also gone through the architectural drawings available for the existing structure. We had also carried out a number of Non-Destructive Tests to estimate the present strength of concrete, and compressive tests are conducted on existing materials and found satisfactory. As per the visual inspection no Cracks are found in Columns, beam, stair, plinth level and No settlements in the foundations. The each floor slab is safe as per the load test result. Based on this, we have worked out a system for correcting the distress of the structure and providing necessary strengthening measures.

We therefore certify that the said building structural work is safe and stable for the building user as mentioned in this Stability for Five (5) Years.

NOTE: If earthquake is occurred at the Richter scale of 5.5 or more, it is necessary to conduct revalidation of Structural Stability Certificate as soon as possible.

Er. SAMIT BISWAS

B.Tech (Civil), B.Arch, F.I.V

Bar# Empaneled Valuer, Building Planner

Member of Institution of Valuer No. L-17535

SMC Regd No B-04, DARJILING No B-64

Cell 943410249, 9832066425

Rajen Koley
RAJEN KOLEY
B.E (CIVIL), M. Tech
STRUCTURAL ENGINEER
EMPANELLED NO: ESE/III/593
KOLKATA MUNICIPAL CORPORATION

ATTESTED

S. P. S. D.
Principal

Notre Dame Academy
Darjeeling

STRUCTURAL STABILITY CERTIFICATE

NAME OF BUILDING: SENIOR SECONDARY BUILDING (BASEMENT+4 STORIED BUILDING), NOTRE DAME SISTERS SOCIETY, AT GANDHI ROAD, WEST POINT, P.S. SADAR, DIST: DARJEELING,

LAND SCHEDULE: MOUZA - DARJEELING, J.L. NO-24, SHEET NO: 45, KHATAN NO. 5633

We had inspected the above referred structure with a view to ascertain the Structural Stability of the building. The structural elements inspected included foundations, RCC columns, RCC beams, and RCC slabs. We had also gone through the architectural drawings available for the existing structure. We had also carried out a number of Non-Destructive Tests to estimate the present strength of concrete, and compressive tests are conducted on existing materials and found satisfactory. As per the visual inspection no Cracks are found in Columns, beam, stair, plinth level and No settlements in the foundations. The each floor slab is safe as per the load test result. Based on this, we have worked out a system for correcting the distress of the structure and providing necessary strengthening measures.

We therefore certify that the said building structural work is safe and stable for the building user as mentioned in this Stability for Five (5) Years.

NOTE: If earthquake is occurred at the Richter scale of 5.5 or more, it is necessary to conduct revalidation of Structural Stability Certificate as soon as possible.

Er. SAMIT BISWAS
B.Tech (Civil), B.Ar, F.I.V
Bar* Empaneled Valuer, Building Planner
Member of Institution of Valuer No. L-17335
SMC Regd No B-04, DARJ. No B-52
Cell: 943410249, 9820066439

Rajen Koley
RAJEN KOLEY
B.E (CIVIL), M. Tech
STRUCTURAL ENGINEER
EMPANELLED NO: ESE/11/593
KOLKATA MUNICIPAL CORPORATION

ATTESTED

Dr. Leena S.N.D
Principal
Notre Dame Academy
Darjeeling

STRUCTURAL STABILITY CERTIFICATE

NAME OF BUILDING: SENIOR SECONDARY BUILDING (BASEMENT+4 STORIED BUILDING), NOTRE DAME SISTERS SOCIETY, AT GANDHI ROAD, WEST POINT, P.S. SADAR, DIST: DARJEELING,

LAND SCHEDULE: MOUZA - DARJEELING, J.L. NO-24, SHEET NO: 45, KHATAN NO. 5633

We had inspected the above referred structure with a view to ascertain the Structural Stability of the building. The structural elements inspected included foundations, RCC columns, RCC beams, and RCC slabs. We had also gone through the architectural drawings available for the existing structure. We had also carried out a number of Non-Destructive Tests to estimate the present strength of concrete, and compressive tests are conducted on existing materials and found satisfactory. As per the visual inspection no Cracks are found in Columns, beam, stair, plinth level and No settlements in the foundations. The each floor slab is safe as per the load test result. Based on this, we have worked out a system for correcting the distress of the structure and providing necessary strengthening measures.

We therefore certify that the said building structural work is safe and stable for the building user as mentioned in this Stability for Five (5) Years.

NOTE: If earthquake is occurred at the Richter scale of 5.5 or more, it is necessary to conduct revalidation of Structural Stability Certificate as soon as possible.

Er. SAMIT BISWAS

B.Tech (Civil), B.Ar. F.I.V

Bar* Empaneled Valuer, Building Planner

Member of Institution of Valuer No. L-17335

SMC Regd No B-04, DARJID No B-52

Cell: 943410249 982056279

Rajen Koley
RAJEN KOLEY
B.E (CIVIL), M. Tech
STRUCTURAL ENGINEER
EMPANELLED NO: ESE/11/593
KOLKATA MUNICIPAL CORPORATION

ATTESTED

Dr. Terry S.N.D.
Principal
Notre Dame Academy
Darjeeling